



R1	1. Megohm
R2	8,200 Ohms
R3	270K
R4	620 Ohms
R5	620 Ohms
R6	470K
R7	8,200 Ohms
R8	2.2 Megohm
R9	4,700 Ohms
R10	1,000 Ohms
R11	4,700 Ohms
C1	20MFD. 25V
C2	.002 MFD. 600V
C3	50 MMF. 500V
C4	.1 MFD. 400V
C5	50MFD. 50V
C6	50MFD. 50V
C7	.003MFD. 600V
C8	20MFD. 450V
C9	20MFD. 450V
C10	35MFD. 350V
T1	GA-40-P
T2	X-3740
L1	GA-10-C
F1	2 AMP. TYPE 3AG
P1	#48 OF #47
S1	SPST SWITCH
V5	6J5
V6	6V6G/GT
V7	6V6G/GT
V8	5V3G/GT
V9	0A2

Gibson Clavioline amplifier.